



Front view




(3) Side view
of
Brush Guard



Twist
Pin
Assembly
(1)
Engaged

(2) mounting
Bracket

Truck side Push Plates




Existing Plates
that remain
on a truck
after a snowplow
is removed.




Page 7 of 7

Back view



(10)
Twist P.N
Assembly
NOT Engaged



Top view

